



**HOOSIER** ACADEMIES<sup>SM</sup>  
Network of Schools

**ASBESTOS INSPECTION NOTICE**

**10/28/18**

**Hoosier Academy of Indianapolis Administrative Office, located at 2855 North Franklin Road,  
Indianapolis, Indiana, 46219**

In compliance with the A.H.E.R.A. regulation (EPA 40 CFR 763 Subpart E), the Hoosier Academy of Indianapolis inspects all portions of its facility where known or assumed asbestos-containing materials exist. Although there is a relatively small amount of asbestos-containing materials in our building. These materials are so contained that they cause no health hazard to the occupants.

In accordance with the requirements outlined under the A.H.E.R.A. rule, the initial inspection of the school building for the presence of asbestos-containing materials was conducted by Micro Air, Inc. of Indianapolis, Indiana in September 2018. The next scheduled six-month periodic surveillance for asbestos-containing materials will be conducted by the school corporation in April 2019. No response actions as defined under the A.H.E.R.A. rule, have been conducted by the school corporation within the last year.

A management plan is available for public inspection, upon request, at the Hoosier Academy of Indianapolis Administrative Office, located at 2855 North Franklin Road, Indianapolis, Indiana, 46219, during normal business hours. The request should be made at least one working day in advance to view materials at the Administrative Office.

It has been, and continues to be, the policy of this corporation to keep the public informed of all matters that pertain to the safety and general health of our students, faculty, and visitors in our schools.

This statement fulfills the requirements of A.H.E.R.A. by the Hoosier Academy of Indianapolis.